

Report 64109 Test Report

Reference	
Fr. Ormstrup	

Application

Testing and classification according to EN 1307, determination of castor chair suitability, stair suitability, resistance to fraying and determination of static electrical propensity.

Test Material

"Highline 80/20 1400 mod350"

Material used in testing was anonymized for laboratory purposes. A detailed sample list is contained in the report.

Issuing and Signatures

Number of pages contained: 14 Original Issue / Vienna 2010-08-10 / Rm/KK21000120

Authorised for Institute DI (FH) Angelika Hönecke

Haver

Technology Build and Live Ing. Hannes Vittek 🕿 18 / vittek@oeti.at



ÖTI – Institut für Ökologie, Technik und Innovation GmbH + Spengergasse 20 + A-1050 Wien + Austria +
Telefon: +43 1 5442543-0 + Fax: +43 1 5442543-10 + Email: office@oeti.at + Web: www.oeti.at +

UniCredit Bank Austria AG BLZ 12000 + Konto 23410378800 + IBAN AT941200023410378800 +

• Swift: BKAUATWW • UID-Nummer: ATU65149029 • FN: 326826b • DVR-Nummer: 0000000 •





Contents

1	Order	2
1.1	Chronology	. 2
1.2	Samples	
2	Findings / Tests performed	. 3
2.1	Description of specimen	. 3
2.2	Determination of mass per unit and pile mass per unit area	3
2.3	Determination of thickness and thickness of wear layer	4
2.4	Calculation of surface pile density and pile fibre volume ratio	
2.5	Determination of number of tufts or loops	
2.6	Determination of the basic requirement of pile carpets	
2.7	Determination of changes in appearance – Drum Test	6
2.8	Determination of the resistance to fraying	
2.9	Classification of pile carpets	7
2.10	Classification of the suitability for use on stairs	
2.11	Determination of the castor chair suitability of textile floor coverings	
2.12	Assessment of static electrical propensity – walking test	
2.13	Determination of total mass of individual tile	9
2.14	Determination of the side length, squareness and straightness of tiles	
2.15	Determination of dimensional changes and distortion out of plane	11
2.16	Classification of pile carpets, additional requirements for pile carpet tiles	12
3	Summary of results	
4	Remarks	14

1 Order

1.1 Chronology

Date	Received	Order
2010-07-16	2010-07-20	Testing and classification according to EN 1307, determination of castor chair suitability, stair suitability, resistance to fraying and determination of static electrical propensity.

1.2 Samples

No.	Received	Sample Identification	Sample Material
1	2010-07-20 (1)	"Highline 80/20 1400 mod350"	Textile floor coverngs, 41 pcs. each 48 x 48 cm

(1) Samples provided by the customer. (2) Sample drawn by ÖTI.



2 Findings / Tests performed

2.1 Description of specimen

Description of specimen according to ISO 2424

Test Results

Sample tested: 1

Dimensions:	tiles	
Manufacturing procedure:	tufted	
Structure of face side:	cut pile	
Coloration of face side:	multicoloured patterned	
Type of backing:	textile nonwoven backing	
Type of fibres at face side *):	80% wool / 20% polyamide (according to the specification by the applicant)	

*) In accordance with the at present valid version of the appropriate European Directives; fibre materials less then 2 % are not considered

According to EN 1307, this is a pile carpet.

2.2 Determination of mass per unit and pile mass per unit area

Test conditions

According ISO 8543 Test atmosphere: 20° C / 65 % rel. humidity Type of shearing apparature: Sharp pointed knife Number of samples: 4

Test results

Tested sample: 1

	mass per unit area	pile mass per unit area
Mean value	3049 g/m²	982 g/m²
Coefficient of variation	2.0 %	1.4 %
Confidence interval (P = 95 %) absolute width	± 98 g/m²	± 23 g/m²

Note:

The pile mass per unit area of pile carpets represents the mass over the carpet-ground which can be sheared with the sharp pointed knife. If other procedures are consulted for the shearing of the pile material, then is to be counted on deviating results. The pile mass per unit area should not be confounded with the pile weight.



2.3 Determination of thickness and thickness of wear layer

Test conditions

Testing according

Determination of thickness according to ISO 1765 Determination of thickness of wear layer according to ISO 1766 Test atmosphere: 20° C / 65 % rel. humidity Shearing methode: Sharp pointed knife Number of samples: 4

Test results

Tested sample: 1

	total thickness	thickness of wear layer
Mean value	10.5 mm	6.1 mm
Coeffizient of variation	0.5 %	1.2 %
Confidence interval (P = 95 %) absolute width	± 0.1 mm	± 0.2 mm

2.4 Calculation of surface pile density and pile fibre volume ratio

Test conditions

The calculation was made according ISO 8543 with integration of the following test results:

Pile material	80% wool / 20% polyamide
Density of pile material	1.28 g/cm ³
Mass of pile per unit area	982 g/m²
Thickness of above the substrate pile	6.1 mm

Test results

Tested sample: 1

Surface pile density	0.161 g/cm ³
Relative surface pile density	12.5 %

2.5 Determination of number of tufts or loops

Test conditions

According to ISO 1763

Test results

Tested sample: 1

Number of tufts or loops / 10 cm	in length direction:	44.1
	in cross direction:	31.5
Number of tufts or loops per dm ² :		1389
Number of tufts or loops per m ² :		138900



2.6 Determination of the basic requirement of pile carpets

Test conditions

According to EN 1307:2008

Test results

Tested sample: 1

Surface structure	cut pile carpet
Pile material	80% wool / 20% polyamide

	Basic requirements	Test results	
Colour fastness to a)			
 ▶ Light 	\geq 5 (pastel shade ^{b)} \geq 4)		
 Rubbing 			
- dry	≥ 3-4		
- wet	≥ 3	Conformity to be	
 Water – change in colour 		declared by the manufacturer for	
- plain carpets	≥ 3-4	each colour	
- other carpets	≥ 4		
 Water – staining ^{c)} 			
all carpets	≥ 2-3		
Fibre bind for all carpets < 80 % Wo	ol		
 Loop pile carpets 	Fuzzing below level of reference photographs		
Cut pile carpets	Loss of mass \leq 25 %		
Colour change ^{d)}			
 Due to spilled water 	≥ 4	Conformity to be declared	
 Due to soiling subsequent to spilled water 	≥ 3	by the manufacturer for each production run	

a) Conformity to be declared by the manufacturer for each colour

^{b)} Pastel shade: colour corresponding to a standard depht ≤ 1/12 (in accordance with EN ISO 105-A01)

c) On multi firbe: worst result

d) Conformity to be declared by the manufacturer

Judgement

The tested material fulfills fulfills the basic requirements of pile carpets according to EN 1307:2008, point 6.

For pile carpets with \ge 80 % wool in the wear layer there are no basic requirements according EN 1307, therefore this floor covering fulfill the basic requirements "a priori"



2.7 Determination of changes in appearance – Drum Test

Test conditions

According to EN 1307 and ISO/TR 10 361 Assessment according EN 1471 Number of drum revolutions: 5 000 and 22 000 Number of specimens: 1

Test results

Tested sample: 1

	5 000 revolutions	22 000 revolutions	
Index of appearance change (median)	3.5	3.0	
Index of colour change (median)	3-4	3	
Main reasons for change	colour + structure colour + str		
Index after colour correction (median)	er colour correction (median) 3.5		
Index after colour correction (mean)	3.6 2.8		
Demages by the treatment	none		

Assessment indices: Index 1 - high change, Index 5 - no change

2.8 Determination of the resistance to fraying

Test conditions

Testing according to EN 1814:2005 Number of test samples: 4 Kind of test sample: tiles

Test results

Tested sample: 1

Damages on cut edge after treatment: none

Judgement

The tested specimen can be classified as resistant to fraying.



2.9 Classification of pile carpets

Test conditions

According to EN 1307:2008

Test results

Tested sample: 1

Surface structure			cut pile carpet
Pile material			80% wool / 20% polyamide
Surface pile weight		[g/m²]	982
Surface pile thickness		[mm]	6.1
Surface pile density		[g/cm ³]	0.161
Number of tufts		[tufts/m ²]	138900
Fibre factor		[FF]	1.72
Tretrad index		[I _{TR}]	
Drum test (Vettermann)	Short term	[5.000 turns]	3.5
	 Long term 	[22.000 turns]	3.0
Resistance to fraying			resistant
Wear index		[Wi]	5.1
Luxury rating factor		[C _F]	47.8

Classification

Type of carpet	Туре 2
Classification for wear	class 33
Classification for change in appearance	class 33
Overall use class	class 33
	61833 55
Luxury rating class	LC 4

Explanations:

Textile floor coverings are classified to their suitability in different use classes. There are two essential characteristics for the classification: wear behaviour and change in appearance. These both characteristics serve the description of the use behaviour in dependence to the intensity of use. The use class assigned to the carpet is the lower one that was reached after the testing of the wear behaviour and change in appearance. The different use classes are described as followed:

Domestic		Commercial		
Class	Use intensity	Class Use intensi		
21	moderate / light			
22	general / medium			
22+	general	31	moderate / light	
23	heavy	32	general	
		33	heavy	



The use- and comfort-classes are corresponding to the following till now common judgements for the wear- and comfort behaviour.

Level of use classification		"use class"
EN 1307:2008	EN 1307:1997	
21	1	low
22	2	normal
22+ / 31	2	normal
23 / 32	3	heavy
33	4	extreme

Luxury rating class	"luxury value"	
LC 1	plain	
LC 2	good	
LC 3	high	
LC 4	luxurious	
LC 5	prestige	

2.10 Classification of the suitability for use on stairs

Test conditions

According to EN 1963; Test methode B: nosing test

Test results

Tested sample: 1

Appearance change*) in the edge area	low appearance change		
*)complete mean			

Classification

According to EN 1307 the specimen can be classified as suitable

"for intensive use"

Note: A workmanlike construction of the stair nose with a rounding radius of at least 10 mm is presupposed to the judgement.

2.11 Determination of the castor chair suitability of textile floor coverings

Test conditions

According to EN 985, Method A Test apparatus: castor chair test equipment, Typ: Feingerätebau Baumberg Castors: according EN 985

Test results

Tested sample: 1

Test duration	change of attribute	Index of colour change *)	Index of appear- ance change *)
5 000 revolutions	colour + structure	2	2.5
25 000 revolutions	colour + structure	1	1.5
Castor chair index (r)	2.3		

*) Note: Index 1 - high change / Index 5 - no change

Damages by the treatment: none



Classification

According the specifications of EN 1307 the specimen can be classified as:

"suitable for occasional use"

2.12 Assessment of static electrical propensity - walking test

Test Conditions

According to ISO 6356 Testing atmosphere: $23 \pm 1 \degree C / 25 \pm 3 \%$ rel. humidity Base plate: Isolating rubber mat on metal plate Sole-material: XS-664P Neolite Pretreatment: none

Test results

Tested sample: 1

Supplied condition					
Measurement 1 Measurement 2 Measurement 3 Mean value					
-1,6 kV	-1,8 kV	-2,4 kV	-1,9 kV		

Judgement

The tested sample in supplied condition can be classified as **antistatic** according EN 14041:2004.

2.13 Determination of total mass of individual tile

Test conditions

According ISO 8543 Test atmosphere: 20° C / 65 % rel. humidity Number of samples: 4

Test results

Tested sample: 1

	total mass of individual tile
Mean value	0.705 kg
Coefficient of variation	1.4 %
Confidence interval (P = 95 %) absolute width	± 0.016 kg



2.14 Determination of the side length, squareness and straightness of tiles

Test condition

According to EN 994 Number of tested specimens: 5 Nominal dimension: Length: 480mm; Width: 480mm

Test results

Tested sample: 1

Determination of dimensions		Length direction	Cross direction
mean length	[mm]	480.2	480.2
min. average length	[mm]	480.2	480.0
max. average length	[mm]	480.3	480.2
difference between the smallest and the largest average length	[mm]	0.1	0.2
max. deviation from mean length	[%]	< 0.1	< 0.1
max. deviation from nominal dimension	[%]	0.1	0.1
Squareness and straightness			
max. deviation	[mm]	< 0.20	
max. deviation	[%]	0.04	



2.15 Determination of dimensional changes and distortion out of plane

Test conditions

According to EN 986

Test results

Tested sample: 1		Dimensional change [%]	
		length	Cross
1. Treatment	1. Measurement	± 0.0	± 0.0
2 hours storage (drying) at 60 °C	2. Measurement	± 0.0	± 0.0
	3. Measurement	± 0.0	± 0.0
	Mean value	± 0.0	± 0.0
2. Treatment	1. Measurement	- 0.1	+ 0.1
2 hours storage in water at 20 °C	2. Measurement	- 0.1	± 0.0
	3. Measurement	- 0.1	± 0.0
	Mean value	- 0.1	± 0.0
3. Treatment	1. Measurement	- 0.2	+ 0.1
24 hours storage (drying) at 60 °C	2. Measurement	- 0.2	+ 0.1
	3. Measurement	- 0.2	± 0.0
	Mean value	- 0.2	+ 0.1
4. Treatment	1. Measurement	- 0.2	+ 0.1
48 hours storage at standard climate	2. Measurement	- 0.2	± 0.0
	3. Measurement	- 0.2	± 0.0
	Mean value	- 0.2	± 0.0

maximum distortion out of plane [mm] after the treatment (step 4):						
specimen 1	specimen 2	specimen 3	Mean value			
2	2	3	2			

Note:

A plus (+) is used to indicate an increase and a minus (-) is used to indicate shrinkage in dimensions.



2.16 Classification of pile carpets, additional requirements for pile carpet tiles

Test conditions

According to EN 1307:2008, annex A

Test results

Tested sample: 1

	Requirements Non adhered Adhered tile		Test results		
	Loose laid	Removable	Permanent		
Total mass of individual tile, ISO 8543	≥ 0,875 kg	≥ 0,625 kg		0.705	
Total mass per unit area, ISO 8543	≥ 3,5 kg/m²	≥ 2,5 kg/m²		3,0	
Dimensions, EN 994	± 0,30 % on nominal dimensions			max. deviation on nominal dimensions longitudinal 0.1 % cross 0.0 %	
	± 0,20	% in the same	max. deviation to the mean length longitudinal 0.1 % cross < 0.1 %		
Squareness and straightness of edges, EN 994	± 0,15 % in both directions			max. deviation < 0.04 %	
Dimension stability,	shrinkage in both directions			max. dimensional	
EN 986	$\leq 0,2$	2 %	≤ 0,4 %	change	
	extension in both directions			longitudinal – 0.2 %	
	$\leq 0,2$	2 %	≤ 0,2 %	cross + 0.1 %	
Curling / doming, EN 986	max. devia part of the sa plane ≤	mple from its		max. curling / max. doming 2 mm	
Damage at cut edge (fraying), EN 1814	no damage			no	

Judgement

The submitted sample fulfils the additional requirements for removeable adhered carpet tiles according EN 1307:2008, Annex A (normative).

Report 64109 • 13 / 14



3 Summary of results

-	-				
Constructive characteristics					
material of use surface(by the applicant)		80% wool / 20% polyamide			
Total mass per unit area		3049 g/m²			
Mass of pile per unit area		982 g/m²			
Total thickness		10.5 mm			
Thickness of pile above the substrate		6.1 mm			
Surface pile density		0.161 g/cm ³			
Number of tufts or loops		138900 /m²			
Basic requirements			fulfilled *)		
Change in appearance – ' (ISO 10 361)	'Vettermann" drum test	Median	Mean value		
assesment after colour	correction – 5000 cycles	Note 3.5	Note 3.6		
assesment after colour correction – 22000 Touren		Note 3.0	Note 2.8		
Classification according EN 1	307				
Carpet category		Type 2			
Basic requirements			fulfilled		
Classification of the wear performance		Class 33			
Classification of the appearance retention		Class 33			
Level of use classification		Class 33			
Use intensity		commercial use 33 "heavy"			
Luxury rating classification		LC4			
Luxury value		LC4 "luxurious"			
Additional caracteristics					
Castor chair suitability (EN	suitable for accasional use				
Antistatic (ISO 6356)					
Walking test (before cleaning)		-1,9 kV			
Suitability for use on stairs	Suitability for use on stairs (EN 1963 method D)		"suitable for intensive use"		
Fraying behaviour (EN 1814)		resistant to fraying			
Additional Requirements for tiles		fulfill	ed ¹⁾		
Total mass of individual tile (ISO 8543)		0.705 kg			
Dimensions (EN 994)	- max. deviation to nominal	0.1 %			
Squareness / straightness of edges (EN 994)	- deviation to nominal	< 0.04 %			
Dimension stability	- length direction	- 0.	2 %		
(ISO 986)	- cross direction	+ 0.1 %			
Curling/doming (ISO 986) ⁵⁾		2 mm			

*)For pile carpets with ≥ 80 % wool in the wear layer there are no basic requirements according EN 1307, therefore this floor covering fulfill the basic requirements "a priori"

¹⁾ Fulfils the requirements for "removable adhered tiles"



4 Remarks

Sample Material

Results of performed tests only refer to the sample material provided.

Without explicit written other agreement testing is destructive and the sample material is transferred to the property of ÖTI, which is entitled to freely decide on storage and disposal.

Quality management and accreditations

All tests and services are performed under a quality management system according to EN ISO 17025.

ÖTI is accredited by several organisations for various tests offered. It also is a Notified Body for several directives with the registration number 0534 (see http://ec.europa.eu/enterprise/newapproach/nando/). The accreditation by the Federal Ministry of Economy, Family and Youth as testing laboratory was repeated under reference 92.714/0560-I/12/2009 (Individual accredited test procedures are marked with the federal laboratory logo), the accreditation for testing and inspection of construction products was given by the OIB (Austrian Institute of Construction Engeineering). Details and other accreditations are given on request and can be found on www.oeti.at.

Issuance

The valid first issue is done in paper and has single-handed signatures. For reference purposes and filing an unsigned electronic duplicate can be delivered in pdf format. Duplicates and translations will be marked accordingly on the cover sheet.

Copyright und Usage Notes

It is pointed out, that any alterations, amendments or falsifications of reports not authorized by the issuer of the report will be prosecuted as civil and criminal offences; this especially to the appropriate requirements of ABGB, UrhG, UWG and criminal law and their respective international equivalents.

Reports are protected under international copyright laws. Written consent of the ÖTI is required for publications (also in excerpt) and reference to tests for public relation purposes. Reports may only be reproduced in full length.

End of Report